















In order to protect consumer legitimate rights, the European Union, UK,USA, Canada, Australia together with other countries in the world has established special notification systems to provide information of products which may cause risk to people health and safety.

A total of 33 notifications of children's toys were declared in EU RAPEX are from Czechia, France, Hungary, Lithuania, Poland, Slovenia, Sweden, Netherlands; 8 notifications in Healthy Canadians official website; 4 notifications in UK official for product safety and Standards website; 2 notification in Australian product safety recalls official website; 3 notifications in CPSC official website during the 37th and the 41th week of 2023. Except the notification in Australian product safety recalls official website, in which the original country of toys are not mentioned, up to 43 notifications of children's toys are from China among all those notifications. Toys were notified because of The product contains magnets with a high magnetic flux., Contain or release small parts, Phthalates content exceeds the limit level, etc.

Risk	Notifying country	Regulation / Standard	Notifica- tion count	Products	Partial Pictures
<b>Choking</b> Contain or release small parts.	France The Nether- lands Poland Slovenia USA Canada	EN 71-1 ASTM F963-17 SOR/2011-17	10	Soft toy Wooden car track Activity cube Set of toy vehicles Rattle toy Plastic toy gun Soft toy with suction cup Plush toy Board Books	
<b>Choking, Injuries</b> Contain or release small parts. The product contains magnets with a high magnetic flux.	Hungary Poland Canada	EN 71-1 SOR/2011-17	9	Magnetic toy figure Magnetic toy Magnetic Building Blocks Magnetic Pen Magnetic Dart Board	

Consumer Testing Technology Co., Ltd.

Guangdong

(Dongguan/Shenzhen/Huizhou/Guangzhou/Zhongshan)

TEL: +86(0)769-8898 9888-884

Taiwan

TEL: +886-0905-989-569 E-mail: tw@cttlab.com Zhejiang (Yiwu/Ningbo)

TEL: 0579-8998 6543

Vietnam

TEL: +84 024 3928 8688 E-mail: vn@cttlab.com Fujian

(Quanzhou/Xiamen) TEL: 0595-6809 9099

Austria

TEL: +43 699 1000 3888 E-mail: eu@cttlab.com Hong Kong

TEL: +852 9319 8131

USA

E-mail: enquiry@cttlab.com http://www.cttlab.com

















#### Continue:

Risk	Notifying country	Regulation / Standard	Notifica- tion count	Products	Partial Pictures
<b>Chemical</b> Phthalates content exceeds the limit level.	Czechia Poland Lithuania	REACH ANNEX XVII	4	Plastic doll Soft plastic toy	Fastion
Environment Lead content exceeds the limit level.	Poland Sweden	RoHS 2 Directive	3	Electric toy Plastic ball	GRAFTSMAN DEPOT
Burns The product is easily flammable and the flame propagation is too high.	France Poland	EN 71-2	2	Fancy dress Toy car	<b>3</b>
Choking The seams come easily apart, making the filling accessible.	France Poland	EN 71-1	2	Soft toy	

Consumer Testing Technology Co., Ltd.

Guangdong

(Dongguan/Shenzhen/Huizhou/Guangzhou/Zhongshan)

TEL: +86(0)769-8898 9888-884

TEL: +886-0905-989-569 E-mail: tw@cttlab.com

Zhejiang

(Yiwu/Ningbo)

TEL: 0579-8998 6543

TEL: +84 024 3928 8688 E-mail: vn@cttlab.com

Fujian

(Quanzhou/Xiamen) TEL: 0595-6809 9099

TEL: +43 699 1000 3888 E-mail: eu@cttlab.com

Hong Kong

TEL: +852 9319 8131

USA

E-mail: enquiry@cttlab.com http://www.cttlab.com















CTT-TT-S23008E

### **Toy Products Recall Notifications-2023 report 8**

#### Continue:

Risk	Notifying country	Regulation / Standard	Notifica- tion count	Products	Partial Pictures
Chemical The felt pens' inks contain a mixture of the preservatives methylchloroisothiazolinone (MCI) and methylisothiazolinone (MI). Dermal contact with MCI and MI containing products can provoke allergic contact dermatitis to sensitised persons.	France	Toy Safety Di- rective EN 71-10 EN 71-11	2	Finger paint Modelling clay	
Chemical, Choking The toy can easily open, leaving the button batteries accessible. A child could put them in the mouth, which could cause damage to the child's gastrointestinal tract or choking.	Hungary	EN 71-1 EN 62115	2	Toy musical instru- ment Toy car	22345
Injuries Loose or broken magnets associated, leading to injuries.	USA	ASTM F963-17	1	Children's Play Tents	
Choking  If a child puts the toy in the mouth and swallows it, it could cause occlusion of the respiratory track or intestinal blockage.	USA	ASTM F963-17	1	Water Beads Activity Kits	

Consumer Testing Technology Co., Ltd.

Guangdong

(Dongguan/Shenzhen/Huizhou/Guangzhou/Zhongshan) TEL: +86(0)769-8898 9888-884

TEL: +886-0905-989-569 E-mail: tw@cttlab.com

Zhejiang (Yiwu/Ningbo)

TEL: 0579-8998 6543

TEL: +84 024 3928 8688 E-mail: vn@cttlab.com

Fujian

(Quanzhou/Xiamen) TEL: 0595-6809 9099

TEL: +43 699 1000 3888 E-mail: eu@cttlab.com

Hong Kong

TEL: +852 9319 8131

USA

E-mail: enquiry@cttlab.com http://www.cttlab.com

















#### Continue:

Risk	Notifying country	Regulation / Standard	Notifica- tion count	Products	Partial Pictures
Choking, Suffocation  The seams come easily apart, making the filling accessible. Plastic packaging is too thin, may cover the mouth and nose causing suffocate.	France	EN 71-1	1	Toy figurines	
Injuries The steering tube is not sufficiently stable. This could cause a child to lose balance and fall, leading to injuries.	UK	Toys (Safety) Regulations 2011	1	Toy swing	
Environment Lead and cadmium content exceeds the limit level.	Sweden	RoHS 2 Directive	1	LED hooverball	
Microbiological The total count of aerobic mesophilic bacteria in this product's filling liquid is too high.	France	Toy Safety Di- rective	1	Toy modelling kit	mole,

Consumer Testing Technology Co., Ltd.

Guangdong

(Dongguan/Shenzhen/Huizhou/Guangzhou/Zhongshan) TEL: +86(0)769-8898 9888-884

TEL: +886-0905-989-569 E-mail: tw@cttlab.com

Zhejiang (Yiwu/Ningbo)

TEL: 0579-8998 6543

TEL: +84 024 3928 8688 E-mail: vn@cttlab.com

Fujian

(Quanzhou/Xiamen) TEL: 0595-6809 9099

TEL: +43 699 1000 3888 E-mail: eu@cttlab.com

Hong Kong

TEL: +852 9319 8131

USA

E-mail: enquiry@cttlab.com http://www.cttlab.com

















#### Continue:

Risk	Notifying country	Regulation / Standard	Notifica- tion count	Products	Partial Pictures
<b>Cuts,Injuries</b> The toy has a sharp edge.	France	EN 71-1	1	Plastic rings toy	
Entrapment, Burns The free ends of the purple ribbon exceed the maximum permitted length. If the ribbon were to get caught on something, the child user may become entrapped which could result in injuries. The material used on the black hat failed flammability tests.	UK	Toys (Safety) Regulations 2011 The General Product Safety Regulations 2005	1	Fancy dress	
Chemical , Suffocation Phthalates content exceeds the limit level. Plastic packaging is too thin, may cover the mouth and nose causing suffocate.	UK	Toys (Safety) Reg- ulations 2011 REACH Regula- tions 2008	1	Fancy dress	

#### Referenced web:

- https://ec.europa.eu/safety-gate-alerts/screen/search?resetSearch=true
- https://www.cpsc.gov/Recalls
- https://recalls-rappels.canada.ca/en/search/site
- https://www.productsafety.gov.au/recalls
- https://www.gov.uk/product-safety-alerts-reports-recalls? Remark: All pictures above are selected from the referenced web.

#### Consumer Testing Technology Co., Ltd.

Guangdong

(Dongguan/Shenzhen/Huizhou/Guangzhou/Zhongshan) TEL: +86(0)769-8898 9888-884

TEL: +886-0905-989-569 E-mail: tw@cttlab.com

Zhejiang (Yiwu/Ningbo)

TEL: 0579-8998 6543

Vietnam

TEL: +84 024 3928 8688 E-mail: vn@cttlab.com

Fujian

(Quanzhou/Xiamen) TEL: 0595-6809 9099

Austria

TEL: +43 699 1000 3888 E-mail: eu@cttlab.com

Hong Kong

TEL: +852 9319 8131

USA

E-mail: enquiry@cttlab.com http://www.cttlab.com



**SAFE GUARD** 











CTT-TT-S23008

# 玩具产品召回通报预警-2023年第08期

为了保障消费者的合法权益,欧盟、英国、美国、加拿大、澳大利亚等国均建立了专门的预警通报机制,对不合格的玩具产品进 行通报。

2023年第37-41周,欧盟RAPEX通报公布的玩具通报案例共35例,来自<mark>捷克、法国、匈牙利、立陶宛、波兰、斯洛文尼亚、瑞</mark> 典、<mark>荷兰</mark>;英国产品安全与标准部门官网4例,加拿大卫生部官网8例,澳大利亚产品安全召回官网2例,美国CPSC官网3例。除了澳 大利亚产品安全召回官网当中通报案例未指明玩具的原产国外,其它所有的通报案例当中与中国有关高达43例。涉及的通报原因包括 含有或易产生小部件,含有高能磁铁,邻苯二甲酸酯含量超标等。

通报原因	通报国	违反法规/标准	通报数量	涉及产品	部分产品图片
窒 <b>息</b> 含有或易产生小部件。	法国 荷兰 波文尼 斯洛 美 軍 加拿大	EN 71-1 ASTM F963-17 SOR/2011-17	10	软体填充玩具 木质车徽 益智游戏玩具 玩具车套铃 玩具车摆铃 塑料玩具枪 带吸盘的软玩具 毛绒虫 儿童	
窒 <b>息 伤害</b> 含有或易产生小部件。 产品含小型高能磁铁。	匈牙利 波兰 加拿大	EN 71-1 SOR/2011-17	9	磁性玩具人偶 磁性玩具 磁性积木 磁性笔 磁性飞镖板	
<b>化学</b> 邻苯二甲酸酯含量超标。	捷克 波兰 立陶宛	REACH ANNEX XVII	4	塑料娃娃塑料软体玩具	Fastion

中鼎检测技术有限公司

广东 (东莞、深圳、惠州、广州、中山) TEL: +86(0)769-8898 9888-884

台湾

TEL: +886-0905-989-569 E-mail: tw@cttlab.com

**浙江**(义乌、宁波)

TEL: 0579-8998 6543

越南

TEL: +84 024 3928 8688 E-mail: vn@cttlab.com

福建 (泉州、厦门)

TEL: 0595-6809 9099

奥地利

TEL: +43 699 1000 3888 E-mail: eu@cttlab.com

香港

E-mail: enquiry@cttlab.com http://www.cttlab.com

TEL: +852 9319 8131

美国















## 玩具产品召回通报预警-2023年第08期

续:

通报原因	通报国	违反法规/标准	通报数 量	涉及产品	部分产品图片
<b>环境</b> 产品铅含量超标。	波兰瑞典	RoHS 2 Directive	3	电动玩具 塑料球	GRAFTSMAN DEPOT
<b>烧伤</b> 产品易燃烧,并且火焰传播速度过快。	法国波兰	EN 71-2	2	化妆舞会服 玩具汽车	<b>19</b>
<b>窒息</b> 玩具接缝容易裂开,导致填充物可触。	法国波兰	EN 71-1	2	软体填充玩具	
化学 含有防腐剂甲基氯异噻唑啉酮 (MCI)和甲基异噻唑啉酮(MI)的混合物。皮肤接触含 MCI和MI的产品可能引起皮肤过敏。	\ <del>+</del>  +	Toy Safety Directive EN 71-10 EN 71-11	2	指画颜料 造型黏土	

中鼎检测技术有限公司

广东 (东莞、深圳、惠州、广州、中山)

TEL: +86(0)769-8898 9888-884

台湾

TEL: +886-0905-989-569 E-mail: tw@cttlab.com

浙江(义乌、宁波)

TEL: 0579-8998 6543

越南

TEL: +84 024 3928 8688 E-mail: vn@cttlab.com

福建 (泉州、厦门)

TEL: 0595-6809 9099

奥地利

TEL: +43 699 1000 3888 E-mail: eu@cttlab.com

香港

E-mail: enquiry@cttlab.com http://www.cttlab.com

TEL: +852 9319 8131

美国













## 玩具产品召回通报预警-2023年第08期

续:

通报原因	通报国	违反法规/标准	通报数量	涉及产品	部分产品图片
化学 窒息 电池舱很容易打开/损坏,使纽扣电池易 于使用。孩子可能会将它们放入口中, 这可能会损坏孩子的胃肠道或窒息。	匈牙利	EN 71-1 EN 62115	2	乐器玩具 玩具汽车	2 3 4 5 6 7 3 t
<b>伤害</b> 磁铁之间易松动或损坏,从而导致 受伤。	無国	ASTM F963-17	1	儿童游戏帐篷	
室 <b>息</b> 产品可能被吞食,并在肠道中膨胀,造成 胃肠道阻塞。	美国	ASTM F963-17	1	水珠玩具套装	WATER BIADS
<b>窒息</b> 玩具接缝容易裂开,导致填充物可触。包 装的塑料袋太薄,可能会盖住嘴巴和鼻 子,导致窒息。	法国	EN 71-1	1	玩偶	

中鼎检测技术有限公司

广东 (东莞、深圳、惠州、广州、中山)

TEL: +86(0)769-8898 9888-884

台湾

TEL: +886-0905-989-569 E-mail: tw@cttlab.com

浙江(义乌、宁波)

TEL: 0579-8998 6543

越南

TEL: +84 024 3928 8688 E-mail: vn@cttlab.com

福建 (泉州、厦门)

TEL: 0595-6809 9099

奥地利

TEL: +43 699 1000 3888 E-mail: eu@cttlab.com

香港

E-mail: enquiry@cttlab.com http://www.cttlab.com

TEL: +852 9319 8131

美国















## 玩具产品召回通报预警-2023年第08期

续:

通报原因	通报国	违反法规/标准	通报数量	涉及产品	部分产品图片
<b>伤害</b> 转向管不够稳定。这可能会导致儿 童失去平衡并摔倒,从而导致受 伤。	英国	Toys (Safety) Regulations 2011	1	玩具秋千	
<b>环境</b> 铅和镉含量超标。	瑞典	RoHS 2 Directive	1	LED悬浮球	
<b>微生物</b> 产品填充液中的好氧嗜温细菌总数 太高。	法国	Toy Safety Directive	1	玩具造型套件	moleges model
<b>割伤 伤害</b> 玩具含有锐利边缘。	法国	EN 71-1	1	塑胶环玩具	

中鼎检测技术有限公司

广东 (东莞、深圳、惠州、广州、中山)

TEL: +86(0)769-8898 9888-884

台湾

TEL: +886-0905-989-569 E-mail: tw@cttlab.com

浙江(义乌、宁波)

TEL: 0579-8998 6543

越南

TEL: +84 024 3928 8688 E-mail: vn@cttlab.com

福建 (泉州、厦门)

TEL: 0595-6809 9099

奥地利

TEL: +43 699 1000 3888 E-mail: eu@cttlab.com

香港

E-mail: enquiry@cttlab.com http://www.cttlab.com

TEL: +852 9319 8131

美国















## 玩具产品召回通报预警-2023年第08期

#### 续:

通报原因	通报国	违反法规/标准	通报数量	涉及产品	部分产品图片
诱捕 燃烧 紫丝带的自由两端超过了允许的最大长度。如果丝带被什么东西缠住,儿童使用者可能会被困住,从而导致受伤。黑帽没有通过燃烧测试。		Toys (Safety) Regulations 2011 The General Product Safety Regulations 2005	1	化妆舞会服	
化学 窒息 邻苯二甲酸酯含量超标。包装的塑料袋太薄,可能会盖住嘴巴和鼻子,导致窒息。	英国	Toys (Safety) Regulations 2011 REACH Regulations 2008	1	化妆舞会服	

#### 参考网站:

- https://ec.europa.eu/safety-gate-alerts/screen/search?resetSearch=true
- https://www.cpsc.gov/Recalls
- https://recalls-rappels.canada.ca/en/search/site
- https://www.productsafety.gov.au/recalls
- https://www.gov.uk/product-safety-alerts-reports-recalls?

备注: 以上图片均来自以上参考网站。

#### 中鼎检测技术有限公司

广东 (东莞、深圳、惠州、广州、中山) 浙江(义乌、宁波) 福建 (泉州、厦门) TEL: +86(0)769-8898 9888-884 TEL: 0579-8998 6543

台湾

TEL: +886-0905-989-569 E-mail: tw@cttlab.com

越南

TEL: +84 024 3928 8688 E-mail: vn@cttlab.com

TEL: 0595-6809 9099

奥地利

TEL: +43 699 1000 3888 E-mail: eu@cttlab.com

香港

E-mail: enquiry@cttlab.com http://www.cttlab.com

TEL: +852 9319 8131

美国